

# Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334589

Location Name: SCHAEFFER-67S93W/11SESE

Inspection Document #: 702801015

Garfield County, CO

SESE Section 11 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SCHAEFFER-67S93W/11SESE  
Location ID: 334589

12/7/22  
+39.456093,-107.736973  
175° S

12/7/22  
+39.455714,-107.736923  
286° W

**Photo 1.** Photos show an overview of the location.



Inspection Photos  
Location Name: SCHAEFFER-67S93W/11SESE  
Location ID: 334589



**Photo 2.** Photo shows interim areas at the west of the location are vegetated with perennial grasses.



**Photo 3.** Photo shows interim areas at the east of the location are vegetated with perennial grasses.