

Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334642

Location Name: PARADISE-67S93W/11NWNE

Inspection Document #: 702801017

Garfield County, CO

NWNE Section 11 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PARADISE-67S93W/11NWNE
Location ID: 334642



Photo 1. Photo taken from the south shows an overview of the location, including interim areas. Interim area vegetation is dominated by introduced perennial grasses.



Inspection Photos
Location Name: PARADISE-67S93W/11NWNE
Location ID: 334642



Photo 2. Photos show production areas. Note tank battery sign has been installed.



Inspection Photos
Location Name: PARADISE-67S93W/11NWNE
Location ID: 334642



Photo 3. Photo shows production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801017