

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403245797

Date Received:

12/01/2022

Spill report taken by:

Araza, Steven

Spill/Release Point ID:

483351

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: <u>CAERUS PICEANCE LLC</u>	Operator No: <u>10456</u>	Phone Numbers
Address: <u>1001 17TH STREET #1600</u>		Phone: <u>(970) 778-2314</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>(970) 778-2314</u>
Zip: <u>80202</u>		Email: <u>jjanicek@caerusoilandgas.com</u>
Contact Person: <u>Jake Janicek</u>		

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403239257

Initial Report Date: 11/23/2022 Date of Discovery: 11/23/2022 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR SESE SEC 34 TWP 1N RNG 98W MERIDIAN 6Latitude: 40.007417 Longitude: -108.370334Municipality (if within municipal boundaries): _____ County: RIO BLANCO

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Reference Location:

Facility Type: WELL SITE☒ Facility/Location ID No 316376Spill/Release Point Name: Yellow Creek Fed. Condensate Tank☐ Well API No. (Only if the reference facility is well) 05- -☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): >=1 and <5Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LANDOther(Specify): RangelandWeather Condition: Partly CloudySurface Owner: FEDERALOther(Specify): WRFO

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Caerus Contractor identified tank overflow into Unlined Earthen Secondary Containment. Well has been shut-in and Vac Truck is in route to recover standing fluids and draw down fluids in tank.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
11/23/2022	Rio Blanco Liaison	Eddie Smercina	970-878-9586	Unable to leave message will email
11/23/2022	CPW	Taylor Elm	970-986-9767	Left voice message
11/23/2022	BLM	Tim Barrett	970-878-9940	Left voice message
11/23/2022	COGCC	Steven Arauza	720-498-5298	Spoke with on phone

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: _____ Public Water System: _____

Residence or Occupied Structure: _____ Livestock: _____

Wildlife: _____ Publicly-Maintained Road: _____

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

Yes Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery _____ (HH:MM)

Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____

Enter the Document Number of the Initial Accident Report, Form 22 _____

Was there damage during excavation? _____

Was CO 811 notified prior to excavation? _____

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): _____

No	Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
	<input type="checkbox"/> The presence of free product or hydrocarbon sheen Surface Water <input type="checkbox"/> The presence of free product or hydrocarbon sheen on Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Surface water
Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 12/01/2022		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	30	10	<input type="checkbox"/>
PRODUCED WATER	0	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): _____		Width of Impact (feet): _____	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined? _____			
Field Observations _____ _____			
Soil/Geology Description: _____ _____			
Rentsac Channery Loam, 5 to 50 percent slopes			
Depth to Groundwater (feet BGS) <u>200</u>		Number Water Wells within 1/2 mile radius: <u>0</u>	
If less than 1 mile, distance in feet to nearest	Water Well _____	None <input checked="" type="checkbox"/>	Surface Water <u>193</u> None <input type="checkbox"/>
	Wetlands _____	None <input checked="" type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>
	Livestock <u>0</u> None <input type="checkbox"/>	Occupied Building _____ None <input checked="" type="checkbox"/>	
Additional Spill Details Not Provided Above: _____			

Cattle are grazing via open range in this area. The depth to groundwater measurement listed above is an estimate based on topography and perennial surface waters located approximately 1.5 miles to the east.

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 12/01/2022

Root Cause of Spill/Release Equipment Failure

Other (specify)

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Above Ground Production Tank

Describe Incident & Root Cause (include specific equipment and point of failure)

The root cause was determined to be a couple of issues that occurred simultaneously. The first was a frozen water dumpline. The freeze/blockage caused water to backup and be conveyed down the condensate dump line into the condensate tank. When the tank filled up it did not equalize into the adjacent tank via an equalizing line due to a malfunctioning ball valve. The valve appeared to be in the open position but the valve stem was broken so the valve body remained closed. This caused the tank to fill to 100% capacity and overflow through the thief hatch. The high level float switch on that specific tank should have sent an alarm to our Operations Control Center but failed to due to a failed wire.

Describe measures taken to prevent the problem(s) from reoccurring:

The malfunctioning valve was replaced and the faulty tank overflow alarm wiring was replaced.

Volume of Soil Excavated (cubic yards):

Disposition of Excavated Soil (attach documentation) ☐ Offsite Disposal ☐ Onsite Treatment

☐ Other (specify)

Volume of Impacted Ground Water Removed (bbls):

Volume of Impacted Surface Water Removed (bbls):

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached, check all that apply)

☐ Horizontal and Vertical extents of impacts have been delineated.

☐ Documentation of compliance with Table 915-1 is attached.

☐ All E&P Waste has been properly treated or disposed.

☐ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No:

☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

Photo documentation and a topo map of the surrounding area are attached to this form.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Print Name: Jake Janicek

Title: EHS Specialist Date: 12/01/2022 Email: jjanicek@caerusoilandgas.com

<u>COA Type</u>	<u>Description</u>
0 COA	

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
403245797	SPILL/RELEASE REPORT(SUPPLEMENTAL)
403245803	PHOTO DOCUMENTATION
403245807	TOPOGRAPHIC MAP
403255729	FORM 19 SUBMITTED

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	Comply with outstanding COAs.	12/09/2022

Total: 1 comment(s)