

# Inspection Photos

12/7/2022

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #324082

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #324082



December 7, 2022



December 7, 2022

**Photo 1:** Photos 1-2 taken from the central areas of the Location. Photos provide an overview of the location from east, southeast, southwest to west. Photos also show well marker left in place.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #324082



December 7, 2022



December 7, 2022

**Photo 2:** See comment under photo 1.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #324082



**Photo 3:** Photo an example showing vegetation on the well site; vegetation appears to be predominantly undesirable and annual species. A follow-up inspection will be conducted in a future growing season to assess desirable plant establishment on the Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location #324082



**Photo 4:** Photo taken from the former battery facility north of the Location. Areas do not appear to be progressing towards 1004 standards; vegetation observed predominantly undesirable plant species such as Kochia.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #324082



**Photo 5:** Photos examples showing noxious weeds observed throughout the Location; photo left shows knapweed; photo right shows chicory.