

# Inspection Photos

12/7/2022

Operator: CAERUS PICEANCE LLC #10456

Location #334733

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334733



**Photo 1:** Photos 1-2 taken from the south end of the Location. Photos provide an overview of the location from east, southeast, southwest to west. Photos also show well marker left in place.

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334733



December 7, 2022



December 7, 2022

**Photo 2:** See comment under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334733



December 7, 2022



December 7, 2022

**Photo 3:** Photos show tank battery facility, and sign at the battery.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334733



**Photo 4:** Photos 4-7 provide examples of tears/holes observed throughout the liner at the tank battery.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334733



**Photo 5:** See comments under photo 4.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334733



December 7, 2022

**Photo 6:** See comments under photo 4.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334733



**Photo 7:** See comments under photo 4.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334733



December 7, 2022



December 7, 2022

**Photo 8:** Photos example showing the interim areas of the Location.