

Inspection Photos
Location Name: Devore 2
Location ID: 332965



Photo 1 WH sign.

Photo 2 WH

Inspection Photos
Location Name: Devore 2
Location ID: 332965



Photo 3 pump jack.

Photo 4 trash cleaned out of PJ house.

Inspection Photos
Location Name: Devore 2
Location ID: 332965



Photo 5 TB sign.

Photo 6 Crude tank has been painted and labels replaced.

Inspection Photos
Location Name: Devore 2
Location ID: 332965



Photo 7 HHS and ECD.

Photo 8 PW tank has been painted and labels replaced.

Inspection Photos
Location Name: Devore 2
Location ID: 332965



Photo 9 Gas Meter Run.