


## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6-66S91W /20SESE

Location ID: 335185



**Photo #8587 From entrance to location.**



**Photo #8588 From entrance to location**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6-66S91W /20SESE

Location ID: 335185



Photo #8589 From entrance to location.



Photo #8590 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6-66S91W /20SESE

Location ID: 335185



Photo #8595 Tank label weathered and not legible.




Photo #8591 Unused equipment.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6-66S91W /20SESE

Location ID: 335185



**Photo #8592 Unused equipment.**



**Photo #8593 Unused equipment.**