

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GGU JOLLEY-66S91W /21SWSW.

Location ID: 335526



Photo #8597 From entrance to location.



Photo #8598 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GGU JOLLEY-66S91W /21SWSW.

Location ID: 335526



Photo #8599 Unused equipment



Photo #8600 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GGU JOLLEY-66S91W /21SWSW.

Location ID: 335526



Photo #8601 Unused equipment.



Photo #8603 Multiple gauge hatches leaking refer to OGIS.