

Environmental Inspection

July 25, 2022

Operator: KP KAKUFFMAN - #46290

Facility ID: 465486; Dwinell TB

Spill/Release ID: 473059

REM #: 15326

Inspection Document #: 6900900228

Jackson County, CO

NESW Section 23 T10N R79W

Alex Fischer

Environmental Supervisor - Western

Colorado, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Tank Battery signage.

Inspection Photos

Location Name: Dwinell TB

Facility ID: 465486

Date: December 6, 2022



Photo 2. Stockpile of impacted material as a result of Spill/Release ID: 473059 under REM 15326.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 6900900228

Inspection Photos
Location Name: Dwinell TB
Facility ID: 465486
Date: December 6, 2022



Photo 3. Front of sign on stockpile of impacted material as a result of Spill/Release ID: 473059 under REM 15326.



Photo 4. Stockpile of impacted material.

Inspection Photos

Location Name: Dwinell TB

Facility ID: 465486

Date: December 6, 2022



Photo 5. Chemical tote “Paraffin Solvent” in lined secondary containment. Note: The secondary containment has an approximate 6’ to 8’ hole in it. This has been observed in previous inspections.



Photo 6. Stockpile of impacted material.

Inspection Photos

Location Name: Dwinell TB

Facility ID: 465486

Date: December 6, 2022




Photo 7. 500 bbl crude Tank #10N79K23 staining on the ground at load valve and coupling. From February 10, 2022 Inspection (Doc #402958096).



Photo 8. 500 bbl crude Tank #10N79K23 staining on the ground at load valve and coupling appears to have been removed. From December 6, 2022 Inspection (Doc #6900900228).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 6900900228

Inspection Photos
Location Name: Dwinell TB
Facility ID: 465486
Date: December 6, 2022



Photo 9. Dwinell #1 well.



Photo 10. Pit Facility ID: 115273 covered with snow.