

Inspection Photos

Location Name: Oxnard East 3130-1ZCH Tank Battery

Location ID: 452516



Photo 1 Sump in southwest corner of lined secondary containment at tank battery.



Photo 2 Sump in southeast corner of secondary containment at separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Oxnard East 3130-1ZCH Tank Battery
Location ID: 452516



Photo 3 Oily waste from blowdown of production lines.



Photo 4 Joint in containment wall with cap in liner.