



Inspection Photos  
Well 081-07282  
Inspection  
Date:9/14/2022

All Photos taken  
by Kris Neidel

**Photo #1 Approximately 130 tons of soil was removed and hauled for disposal as E&P waste.**





Inspection Photos  
Well 081-07282  
Inspection  
Date:9/14/2022

All Photos taken  
by Kris Neidel

Photo #2 wellhead is visible in excavation. Soil was removed until visible contamination was not obvious. Soil samples were observed by COGCC staff, Kris Neidel.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources