

Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 324128

Location Name: JOY-67S93W/11NWNE

Inspection Document #: 702801021

Garfield County, CO

NWNE Section 11 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: JOY-67S93W/11NWNE
Location ID: 324128



Photo 1. Photo taken from the south shows an overview of the location, including interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801021

Inspection Photos
Location Name: JOY-67S93W/11NWNE
Location ID: 324128



Photo 2. Photos show production areas.



Inspection Photos

Location Name: JOY-67S93W/11NWNE

Location ID: 324128



Photo 3. Photo shows production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801021

Inspection Photos
Location Name: JOY-67S93W/11NWNE
Location ID: 324128



Photo 4. Photo shows the pad surface is stable at the time of this inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801021

Inspection Photos

Location Name: JOY-67S93W/11NWNE

Location ID: 324128



Photo 5. Photos show interim areas to the northwest (left) and southeast (right) appear dominated by introduced perennial grasses and native shrubs.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801021