

# Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334670

Location Name: MILLER-67S93W/2NWSE

Inspection Document #: 702801025

Garfield County, CO

NWSE Section 2 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MILLER-67S93W/2NWSE  
Location ID: 334670



Photo 1. Photos show production areas.



Inspection Photos  
Location Name: MILLER-67S93W/2NWSE  
Location ID: 334670



**Photo 2.** Photo shows production areas.



Inspection Photos  
Location Name: MILLER-67S93W/2NWSE  
Location ID: 334670



**Photo 3.** Photo shows an unidentified soil stockpile at the southwest of the location.



Inspection Photos  
Location Name: MILLER-67S93W/2NWSE  
Location ID: 334670



**Photo 4.** Photos show interim areas to the southeast appear dominated by introduced perennial grasses.