

# Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334578

Location Name: MILLER-67S93W/11SWNE

Inspection Document #: 702801029

Garfield County, CO

SWNE Section 11 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MILLER-67S93W/11SWNE  
Location ID: 334578



**Photo 1.** Photo taken from the south shows an overview of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801029

Inspection Photos  
Location Name: MILLER-67S93W/11SWNE  
Location ID: 334578



**Photo 2.** Photos show production areas.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Number: 702801029



Inspection Photos  
Location Name: MILLER-67S93W/11SWNE  
Location ID: 334578



**Photo 3.** Photo shows production areas.



Inspection Photos  
Location Name: MILLER-67S93W/11SWNE  
Location ID: 334578



**Photo 4.** Photos show interim areas to the west (left) and north (right) appear dominated by introduced perennial grasses.

