

# Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334602

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Inspection Document #: 702801031

Garfield County, CO

NWSE Section 11 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE  
Location ID: 334602



**Photo 1.** Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801031

Inspection Photos  
Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE  
Location ID: 334602



**Photo 2.** Photo shows production areas. Separator piping is open ended/uncapped, allowing for wildlife access.



## Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Location ID: 334602



**Photo 3.** Photos show interim areas to the west (left) and east (right) appear dominated by introduced perennial grasses and occasional native shrubs.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801031