

# Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 324074

Location Name: MILLER-67S93W/11NWSE

Inspection Document #: 702801033

Garfield County, CO

NWSE Section 11 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MILLER-67S93W/11NWSE  
Location ID: 324074



Photo 1. Photos show production areas.



Inspection Photos  
Location Name: MILLER-67S93W/11NWSE  
Location ID: 324074



**Photo 2.** Photo shows production areas.



Inspection Photos  
Location Name: MILLER-67S93W/11NWSE  
Location ID: 324074



**Photo 3.** Photos show interim areas to the west (left) and east (right) appear dominated by introduced perennial grasses and occasional native shrubs.