

Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 324070

Location Name: MILLER-67S93W/11SWSE

Inspection Document #: 702801035

Garfield County, CO

SWSE Section 11 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MILLER-67S93W/11SWSE
Location ID: 324070



Photo 1. Photo taken from the east shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission


Department of Natural Resources

Inspection Number: 702801035

Inspection Photos
Location Name: MILLER-67S93W/11SWSE
Location ID: 324070



Photo 2. Photos show production areas.



Inspection Photos
Location Name: MILLER-67S93W/11SWSE
Location ID: 324070



Photo 3. Photo shows production areas.



Inspection Photos
Location Name: MILLER-67S93W/11SWSE
Location ID: 324070



Photo 4. Photos show interim areas to the south (left) and north (right) appear dominated by introduced perennial grasses.