

Inspection Photos  
Location: Yoxall Farms Manifold  
Facility ID: 477437



Photo 1 –

Photo 2 –

# Inspection Photos

Location

Facility ID:



Photo 3 –

Photo 4 – Visible staining and odor

# Inspection Photos

Location

Facility ID:



Photo 5 –

Photo 6 – Visible staining and odor

Inspection Photos  
Location  
Facility ID:




Photo 7 – Visible staining and odor

Photo 8 –

Inspection Photos  
Location  
Facility ID:



Photo 9 –

Photo 10 –

Inspection Photos  
Location  
Facility ID:



Photo 11 –

Photo 12 –

Inspection Photos  
Location  
Facility ID:



Photo 13 –

Photo 14 – Fencing has fallen

Inspection Photos  
Location  
Facility ID:



Photo 15 –