

Inspection Photos

December 9, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 421020

Location Name: Shaeffer/24-5H (J12W)

Inspection Document #: 702801044

Garfield County, CO

NWSE Section 12 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Shaeffer/24-5H (J12W)
Location ID: 421020



Photo 1. Photos show an overview of the western/upper (left) and eastern/lower (right) production pads.



Inspection Photos
Location Name: Shaeffer/24-5H (J12W)
Location ID: 421020




Photo 2. Photos show unused equipment (four (4) risers) at the separator at the southeast of the upper production pad. Risers are LOTO, however tags are in disrepair (right).

Inspection Photos
Location Name: Shaeffer/24-5H (J12W)
Location ID: 421020



Photo 3. Photos show unused equipment (two (2) risers) at the separators at the northeast of the lower production pad.

Inspection Photos
Location Name: Shaeffer/24-5H (J12W)
Location ID: 421020



Photo 4. Photos show BMPs to prevent wildlife access to piping at tank battery are absent.



Inspection Photos
Location Name: Shaeffer/24-5H (J12W)
Location ID: 421020



Photo 5. Photos show wells at the upper (left) and lower (right) production pads.



Inspection Photos
Location Name: Shaeffer/24-5H (J12W)
Location ID: 421020



Photo 6. Photos show interim areas to the west (left) and east (right) appear dominated by introduced perennial grasses. Snow cover and dormant season prevented full vegetation assessment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801044