

WELL



00401168

RM

LOCATION SESE 22-33-58
OPERATOR NCRA
LEASE MADDERN #4

FIELD ROMAN NOSE NORTH
COUNTY ADAMS

DATE OF INSPECTION BEFORE/DURING DRILLING _____

RIG _____ SURFACE CASING SIZE _____ DEPTH SET _____
BOP'S _____ RETURNS _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ CMT VOL _____
COMMENTS _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ HOLE OPEN? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED _____ OPEN _____
WELLHEAD SYSTEM INSTALLED? _____
TANKS _____ HEATERS _____
SKIM PITS _____
LEASE SIGN: YES _____ NO _____ TANK I.D.: YES _____ NO _____ NA _____
COMMENTS _____

DATE OF AL/DA/PA INSPECTION 7/31/87

DATE PLUGGED: _____	PITS BACKFILLED: YES _____ NO <input checked="" type="checkbox"/>
HOLE PLUGGED: YES _____ NO <input checked="" type="checkbox"/>	SITE CLEAN: YES _____ NO <input checked="" type="checkbox"/>
BOND RELEASE OK: YES _____ NO <input checked="" type="checkbox"/>	HOLE MARKER: YES _____ NO <input checked="" type="checkbox"/>

COMMENTS CAZA RIG #2 at LOCATION - HOLE IS OPEN - MAY YES BECOMPLETED AS PR-O-V

DATE APD EXPIRED _____

PA INSPECTION RESULTS: PASS(Y) _____ FAIL(N) ☒

PERMIT # 57-423
API # 05-001-08833
INSPECTOR SSK

TURNKEY OPERATION, CAZA SUPPOSED TO RESTORE LOCATION.

SSK