

Inspection Photos

December 9, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334757

Location Name: COOK-67S93W/12SESE

Inspection Document #: 702801047

Garfield County, CO

SESE Section 12 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: COOK-67S93W/12SESE
Location ID: 334757



Photo 1. Photos shows and overview of the location (left) and production areas (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801047

Inspection Photos
Location Name: COOK-67S93W/12SESE
Location ID: 334757



Photo 2. Photos show interim areas to the south (left) and west (right) appear dominated by introduced perennial grasses. Snow cover and dormant season prevented full vegetation assessment.

