

Inspection Photos

December 9, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334560

Location Name: KRK-67S92W/7NENW

Inspection Document #: 702801049

Garfield County, CO

NENW Section 7 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: KRK-67S92W/7NENW

Location ID: 334560



Photo 1. Photo shows four (4) LOTO risers within the tank battery. Unused riser equipment must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801049

Inspection Photos
Location Name: KRK-67S92W/7NENW
Location ID: 334560



Photo 2. Photos show an overview of the location from the southeast (left) and production areas (right).

Inspection Photos
Location Name: KRK-67S92W/7NENW
Location ID: 334560



Photo 3. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801049

Inspection Photos
Location Name: KRK-67S92W/7NENW
Location ID: 334560



Photo 4. Photos show interim areas to the northwest (left) and northeast (right) appear dominated by introduced perennial grasses. Snow cover and dormant season prevented full vegetation assessment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801049