

Inspection Photos

December 9, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334612

Location Name: BENZEL-67S93W/1SESE

Inspection Document #: 702801055

Garfield County, CO

SESE Section 1 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BENZEL-67S93W/1SESE
Location ID: 334612



Photo 1. Photos show production areas.



Inspection Photos
Location Name: BENZEL-67S93W/1SESE
Location ID: 334612



Photo 2. Photo shows production areas.



Inspection Photos
Location Name: BENZEL-67S93W/1SESE
Location ID: 334612



Photo 3. Photos show interim areas to the west appear dominated by introduced perennial grasses and occasional native shrubs. Snow cover and dormant season prevented full vegetation assessment.

