

Inspection Photos

December 9, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 324115

Location Name: BJM-66S92W/31SESW

Inspection Document #: 702801058

Garfield County, CO

SESW Section 31 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BJM-66S92W/31SESW
Location ID: 324115



Photo 1. Photo taken from the west shows an overview of the location.



Inspection Photos
Location Name: BJM-66S92W/31SESW
Location ID: 324115



Photo 2. Photos show production areas.



Inspection Photos
Location Name: BJM-66S92W/31SESW
Location ID: 324115



Photo 3. Photos show interim areas to the south appear dominated by introduced perennial grasses and occasional native shrubs. Snow cover and dormant season prevented full vegetation assessment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801058