

Inspection Photos

December 9, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 333111

Location Name: B J M-66S92W/31NWSE

Inspection Document #: 702801062

Garfield County, CO

NWSE Section 31 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: B J M-66S92W/31NWSE
Location ID: 333111



Photo 1. Photo taken from the east shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801062

Inspection Photos
Location Name: B J M-66S92W/31NWSE
Location ID: 333111



Photo 2. Photos show production areas.



Inspection Photos
Location Name: B J M-66S92W/31NWSE
Location ID: 333111



Photo 3. Photo shows production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801062

Inspection Photos
Location Name: B J M-66S92W/31NWSE
Location ID: 333111



Photo 4. Photos show interim areas to the west appear dominated by introduced perennial grasses and rabbitbrush. Snow cover and dormant season prevented full vegetation assessment.

