

Inspection Photos

December 9, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334913

Location Name: BJM-67S92W/6N2SE

Inspection Document #: 702801066

Garfield County, CO

NESE Section 6 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BJM-67S92W/6N2SE
Location ID: 334913

12/9/22
+39.471085,-107.701681
98° E



Photo 1. Photo taken from the west shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801066

Inspection Photos
Location Name: BJM-67S92W/6N2SE
Location ID: 334913



Photo 2. Photos show production areas.



Inspection Photos
Location Name: BJM-67S92W/6N2SE
Location ID: 334913



Photo 3. Photos show interim areas at the southeast appear dominated by rabbitbrush. Introduced perennial grasses are also present. Snow cover and dormant season prevented full vegetation assessment.

