

# Inspection Photos

December 9, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334838

Location Name: KRK-67S92W/7NWNE

Inspection Document #: 702801068

Garfield County, CO

NWNE Section 7 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: KRK-67S92W/7NWNE  
Location ID: 334838



**Photo 1.** Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801068

## Inspection Photos

Location Name: KRK-67S92W/7NWNE

Location ID: 334838



**Photo 2.** Photos show production areas (left) and tubing at separators lacks BMPs to prevent wildlife access (right).



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801068

Inspection Photos  
Location Name: KRK-67S92W/7NWNE  
Location ID: 334838



**Photo 3.** Photos show interim areas to the south appear dominated by rabbitbrush and introduced perennial grasses. Snow cover and dormant season prevented full vegetation assessment.

