

Violation of order

WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)



Well Name #2 Linnebur API Number 05 - 001 - 6902
Operator Huckabay Permit # 74-0703
Location W NWSE 31-35 59 County Adams
Field Lone Tree Inspector EBB

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) Fail(N) Date ND DG WO PR SI TA X

Date of Inspection Before/During Drilling

Surf. Csg. Size Setting Depth Cmt. Vol. WOC time
Consistent with APD casing Program? YES NO Returns
Rig BOP'S Stage Tool Depth Cmt. Vol.

Date of Inspection Before/During/After Completion

Prod. Csg. Set? Completion Rig/Activity
Drilling Pits: Closed Open Wellhead Installed: Sign: Yes No
Tank ID: Yes No N/A Skim Tank/Pit: Prod. Tanks: () BBLs
Equipment Meter Run: Yes No
Bradenhead Press: Fluid: No Yes Type Well Cat.

AL/PA/DA Inspection

Date Plugged: Date Permit Expired:
Hole Plugged: Yes No X Pits Backfilled: Yes No
Material Buried: Yes No N/A Site Clean: Yes No
Bond Release OK: Yes No Fed Hole Marker: Yes No

Date of Safety/Status Inspection 9-1-92

Comments: Commission ORDER TO PULL CSG.
Well is presently SI w/ 2" valve, swedged to 5 1/2"
All surface equipment moved off.
(Bull plug & valve w/ swedge to prod CSG.)

Violations: Yes 7 No Notice Sent: Yes No Date Sent: