

Inspection Photos
Location Name: PETTINGER-66N64W/2SWSE
Location #: 305860



Photo #1
Pettinger 34-2 (123-23591) Wellsite
Shut-In | SI



Photo #2
Pettinger 34-2, 33-2, 43-2 Battery site
Inactive | Shut-down
Formerly served:
Pettinger 44-2 ;
Plugged & Abandoned | PA

Inspection Photos
Location Name: PETTINGER-66N64W/2SWSE
Location #: 305860



Photo #3
Pettinger 34-2, 33-2, 43-2 Battery site
Inactive | Shut-down
Tank(s): SE corner



Photo #4
Pettinger 34-2, 33-2, 43-2 Battery site
Inactive | Shut-down
Separator, ECDs

Inspection Photos
Location Name: PETTINGER-66N64W/2SWSE
Location #: 305860



Photo #5

Pettinger 34-2, 33-2, 43-2 Battery site

Inactive | Shut-down

Battery sign