

Inspection Photos
Location Name: PETTINGER-66N64W/2SESE
Location #: 305154



Photo #1
Pettinger 44-2 (123-22572) Wellsite
Plugged & Abandoned | PA
NOT cut / capped



Photo #2
Pettinger 34-2, 33-2, 43-2 Battery site
Inactive | Shut-down
Formerly served:
Pettinger 44-2 ; Plugged & Abandoned | PA
Equipment documented: Loc. # 305860