

Inspection Photos

API: 071-06344

Operator: OGRIS OPERATING LLC

Inspection Date: 12/16/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06344 | Date: 12/16/2022

Inspection Photos



Photo 1. Facing southwest toward the wellsite.



Inspection Photos



Photo 2. There is ice build up at the wellhead which appears to be leaking.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06344 | Date: 12/16/2022

Inspection Photos



Photo 3. Facing toward the lined pit. The electric fence needs maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06344 | Date: 12/16/2022