

Inspection Photos

API: 071-08321

Operator: OGRIS OPERATING LLC

Inspection Date: 12/16/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 12/16/2022

Inspection Photos



Photo 1. Facing southwest at the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 12/16/2022

Inspection Photos



Photo 2. Facing southeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 12/16/2022

Inspection Photos



Photo 3. The engine compressor appears to be leaking oil which has spilled over on the surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08321 | Date: 12/16/2022