

# Inspection Photos

API: 071-07944

Operator: OGRIS OPERATING LLC

Inspection Date: 12/16/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07944 | Date: 12/16/2022

## Inspection Photos



**Photo 1.** Facing west at the road in the canyon bottom.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07944 | Date: 12/16/2022



## Inspection Photos



**Photo 2.** Facing west along the road. The culverts along the road are maintained and road appears to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07944 | Date: 12/16/2022

## Inspection Photos



**Photo 3.** Facing west along the road. The culverts along the road are maintained and road appears to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07944 | Date: 12/16/2022



## Inspection Photos



**Photo 4.** Facing toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07944 | Date: 12/16/2022