

Inspection Photos  
Location Name: Conoco Fee 66 #492  
Location ID:322273



Photo 1 well head



Photo 2 unused plastic tote

Inspection Photos  
Location Name: Conoco Fee 66 #492  
Location ID:322273



Photo 3 Stairs in disrepair considered unused equipment. Trash : rocks wood dead weeds. Plastic tote unused equipment

Photo 4 debris around crude oil tank.

Inspection Photos  
Location Name: Conoco Fee 66 #492  
Location ID:322273



Colorado Oil and Gas Conservation Commission  
38.36634, -105.14256, 1614.0m  
Dec 19, 2022 1:27:25 PM



Colorado Oil and Gas Conservation Commission  
38.36634, -105.14257, 1613.0m  
Dec 19, 2022 1:27:51 PM

Photo 5 Stained soil under load out container.

NFPA placard peeling not legible.

**Inspection Photos**  
**Location Name: Conoco Fee 66 #492**  
**Location ID:322273**

