

Inspection Photos
Location Name: Rob Hiawatha #2
Location ID: 322265



Photo 1 Location sign and crude oil tank



Photo 2 Well head stained soil and no braden head not plumbed to surface

Inspection Photos
Location Name: Rob Hiawatha #2
Location ID: 322265



Photo 3 Storm water erosion near well head



Photo 4 loc pic