

Inspection Photos
Location Name: Straudinger 1-31H
Location ID: 424744



Colorado Oil and Gas Conservation Commission
40.62451, -104.24217, 4914.4ft, 121°
12/14/2022 13:00:32

Photo 1 – Tank Battery



Colorado Oil and Gas Conservation Commission
40.6244, -104.24212, 4927.1ft, 113°
12/14/2022 13:00:41

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Straudinger 1-31H
Location ID: 424744



Photo 3 – Heater Treater



Photo 4 – ECD and Flare

Inspection Photos
Location Name: Straudinger 1-31H
Location ID: 424744



Photo 5 – Wellhead



Photo 6 – Oily Waste in Containment

Inspection Photos
Location Name: Straudinger 1-31H
Location ID: 424744



Photo 7 – Oily Waste



Photo 8 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Straudinger 1-31H
Location ID: 424744



Photo 9 – Stained Soil at Gas Engine