

Final Reclamation Inspection

December 15, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 330420

Inspection Document #: 697504454

Weld County, CO

SESE Section 3 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-KNOX #16-3
Location ID: 330420



Photo 1. COGCC GISOnline aerial imagery from 2019 illustrates the well location (red circle) and associated access road. The associated tank battery is still active.

Inspection Photos
Location Name: HSR-KNOX #16-3
Location ID: 330420



Photo 2. Photo taken from a portion of the well location access road, facing North. Photo illustrates the limited establishment of grass species observed and it is predominately bare ground.

Note- vehicle traffic (not from COGCC) and prairie dog burrows.



Photo 3. Photo taken from the central well location, facing North. See comments under Photo 2.

Inspection Photos

Location Name: HSR-KNOX #16-3

Location ID: 330420



Photo 4. Photo taken from the central well location, facing East. See comments under Photo 2.



Photo 5. Photo taken from the central well location, facing South. See comments under Photo 2.

Inspection Photos

Location Name: HSR-KNOX #16-3

Location ID: 330420



Photo 6. Photo taken from the east central well location, facing North. Photo illustrates the establishment of desirable plant species.



Photo 7. Close up photo taken from the east central well location. See comments under Photo 6.

Inspection Photos
Location Name: HSR-KNOX #16-3
Location ID: 330420



Photo 8. National Wetlands Inventory aerial illustrates Riverine habitat, Freshwater Emergent and Freshwater Forested/Shrub wetland downgradient of location.