

Final Reclamation Inspection

December 15, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 306134

Inspection Document #: 697504461

Weld County, CO

NWNW Section 3 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SHUR VIEW #18-3
Location ID: 306134



Photo 1. COGCC GISOnline aerial imagery from 2019 illustrates the well location (red circle) and associated tank battery that is still active.

Inspection Photos
Location Name: SHUR VIEW #18-3
Location ID: 306134



Photo 2. Photo taken from the western well location, facing East. Photo illustrates the location is predominately bare ground. It appears that a recent flowline removal (red arrow) from another well may have been removed within portion of the well location which could account for some of the vehicle traffic. Operator should ensure that no vehicle traffic continues on the reclamation area.



Photo 3. Photo taken from the well location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: SHUR VIEW #18-3
Location ID: 306134



Photo 4. Photo taken from the well location, facing West. Photo illustrates where the believed flowline was removed due to the recent disturbance.



Photo 5. Photo taken from the well location, facing North. See comments under Photo 2 and 4.

Inspection Photos
Location Name: SHUR VIEW #18-3
Location ID: 306134



Photo 6. Photo taken from the well location, facing East. See comments under Photo 4.



Photo 7. Photo taken from the eastern well location, facing West. See comments under Photo 2.

Inspection Photos
Location Name: SHUR VIEW #18-3
Location ID: 306134



Photo 8. National Wetlands Inventory aerial illustrates Riverine habitat downgradient of location.