

Inspection Photos

API: 099-06275

Operator: EOG RESOURCES INC

Inspection Date: 12/20/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06275 - Date: 12/20/2022

Inspection Photos



Photo 1. Drone photo facing southeast toward the location. Location appears to be restored. There are drilling pipe casing that remains shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06275 - Date: 12/20/2022

Inspection Photos



Photo 2. Drone photo facing down at the location. Location appears to be restored. There are drilling pipe casing that remains shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06275 - Date: 12/20/2022