

Inspection Photos

API: 099-06066

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 12/20/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06066 | Date: 12/20/2022

Inspection Photos



Photo 1. The abandoned gas separator still remains at the location shown at red arrow. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06066 | Date: 12/20/2022

Inspection Photos



Photo 2. Facing east. There is abandoned gas separator that remains at the location. There is also undesirable weeds growing around the abandoned equipment. Previous corrective action was not completed. Photo taken 11/30/21.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06066 | Date: 12/20/2022

Inspection Photos



Photo 3. Facing west. There is abandoned gas separator that remains at the location. There is also undesirable weeds growing around the abandoned equipment. Previous corrective action was not completed. Photo taken 11/30/21.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06066 | Date: 12/20/2022