

Inspection Photos

API: 061-06041

Operator: WESTERN OPERATING COMPANY

Inspection Date: 12/20/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06041 - Date: 12/20/2022

Inspection Photos



Photo 1. Facing west at the beginning of the access road. The cattleguard has been removed and the road regraded. It does not appear reclamation including seeding has been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 12/20/2022

Inspection Photos



Photo 2. Facing west toward the access road. This area needs to be leveled out and reclaimed. It does not appears reclamation including seeding has been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 12/20/2022