

# Inspection Photos

API: 061-05145

Operator: WESTERN OPERATING COMPANY

Inspection Date: 12/20/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05145 - Date: 12/20/2022

## Inspection Photos



**Photo 1.** Facing south toward the location. The access road has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05145 - Date: 12/20/2022

## Inspection Photos



**Photo 2.** Facing south toward the location. The location has been recontoured and decompacted. Soils have not been seeded and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05145 - Date: 12/20/2022

## Inspection Photos



**Photo 3.** The electric powerline which dead ends at the location must be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05145 - Date: 12/20/2022