

Inspection Photos

API: 061-05143

Operator: WESTERN OPERATING COMPANY

Inspection Date: 12/20/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-05143 | Date: 12/20/2022

Inspection Photos



Photo 1. Facing toward the tank battery. It appears a recent spill occurred at the tank contained inside the bermed area. Stained soils need to be cleaned up and removed.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 12/20/2022

Inspection Photos



Photo 2. It appears a recent spill occurred at the tank contained inside the bermed area. Stained soils need to be cleaned up and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 12/20/2022

Inspection Photos



Photo 3. There is a historic spill area that extends 180' north from the tank battery site. There is no vegetation growth in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 12/20/2022

Inspection Photos



Photo 4. Facing northwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 12/20/2022

Inspection Photos



Photo 5. There is oily material being stored in this containment which needs to be removed and properly disposed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05143 | Date: 12/20/2022