

Inspection Photos

API: 061-06023

Operator: WESTERN OPERATING COMPANY

Inspection Date: 12/20/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06023 | Date: 12/20/2022

Inspection Photos



Photo 1. Facing south toward the tank battery facility. The tank was removed and soils have been excavated in this area. Remediation project: 20712



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 12/20/2022

Inspection Photos



Photo 2. The berms around the soil piles have been constructed larger but were not compacted. Also, no liner was observed under the contaminated soils. Contaminated soils should be removed and properly disposed ASAP.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06023 | Date: 12/20/2022

Inspection Photos



Photo 3. Facing southeast toward the tank battery location. Straw wattles have been installed along the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 12/20/2022

Inspection Photos



Photo 4. Facing toward the south side of the location. Soil is being hauled in and stored on the location. Temporary erosion controls will be need to prevent erosion of the loose soils.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 12/20/2022

Inspection Photos



Photo 5. Facing north at the southwest side of the tank battery location. Additional BMP's should be installed on the down gradient side shown at red line down gradient of soil stock pile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 12/20/2022

Inspection Photos



Photo 6. Facing southwest toward the area where the spill occurred. Remediation project: 20712. Some areas have been excavated more than other areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 12/20/2022

Inspection Photos



Photo 7. Located at the western side of the spill area. There is an excavated hole at this area approximately 12'x12'6'. There are still areas of oil stained soils at the surface (Bottom left) and 2ft. Down into the excavation area (right photo). Further excavation is needed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 12/20/2022

Inspection Photos



Photo 8. Drone aerial photo facing west toward the battery and wellsite. There is a remediation project in process. Photo taken on 10/12/2022.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 12/20/2022

Inspection Photos



Photo 9. Drone aerial photo facing east toward the battery and remediation project. Photo taken on 10/12/2022.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 12/20/2022