

Inspection Photos
Location Name: CBO-67N63W/32SESW
Location #: 306148



Photo #1
CBO 24-32 (123-24060) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 260 yds.



Photo #2
CBO 24-32, 14-32 Battery site
Abandoned: ALL Equipment Removed