

# Inspection Photos

API: 061-06799

Operator: STRACHAN EXPLORATION INC

Inspection Date: 12/21/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06799 | Date: 12/21/2022

## Inspection Photos



**Photo 1.** Center of the location facing north. The location consists mostly of undesirable weeds. Reclamation has not been completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06799 | Date: 12/21/2022

## Inspection Photos



**Photo 2.** Center of the location facing west. The location consists mostly of undesirable weeds. Reclamation has not been completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06799 | Date: 12/21/2022

## Inspection Photos



**Photo 3.** Center of the location facing south. The location consists mostly of undesirable weeds. Reclamation has not been completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06799 | Date: 12/21/2022

## Inspection Photos



**Photo 4.** Center of the location facing east. The location consists mostly of undesirable weeds. Reclamation has not been completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06799 | Date: 12/21/2022

## Inspection Photos



**Photo 5.** View of undesirable weeds (Kochia) observed throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06799 | Date: 12/21/2022

## Inspection Photos



**Photo 6.** Facing east toward the surrounding undisturbed field consisting of desirable vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06799 | Date: 12/21/2022