

Inspection Photos

API: 061-06882

Operator: CHESAPEAKE OPERATING LLC

Inspection Date: 12/21/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06882 | Date: 12/21/2022

Inspection Photos



Photo 1. Facing west at the beginning of the access road which remains per approved variance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06882 | Date: 12/21/2022

Inspection Photos



Photo 2. Facing west along the access road shown on right side . The area on the left is disturbance with bare soils that needs to be reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06882 | Date: 12/21/2022

Inspection Photos



Photo 3. Facing northwest toward the location. The location has not established a desirable vegetation cover and there are large areas with no vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06882 | Date: 12/21/2022

Inspection Photos



Photo 4. Facing north toward the location. The location has not established a desirable vegetation cover and there are large areas with no vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06882 | Date: 12/21/2022

Inspection Photos



Photo 5. Northside of the location facing west. The location has not established a desirable vegetation cover and there are large areas with no vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06882 | Date: 12/21/2022

Inspection Photos



Photo 6. Southwest corner of the location facing northeast. The location has not established a desirable vegetation cover and there are large areas with no vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06882 | Date: 12/21/2022

Inspection Photos



Photo 7. Facing down toward the ground cover which shows no desirable vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06882 | Date: 12/21/2022

Inspection Photos



Photo 8. Facing south toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06882 | Date: 12/21/2022