

# Final Reclamation Inspection

September 2nd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 305017

Inspection Document #: 701900582

SWSE Section 33 T2S R43W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Renzelman 34-33  
Location ID: 305017



**Photo 1.** 2019 aerial imagery of the well pad and access road. Note: tank battery remains for the producing Ekberg 2-33 well API #125-07185.

Inspection Photos  
Location Name: Renzelman 34-33  
Location ID: 305017



**Photo 2.** Overview photo of the well pad taken at ground level from the western edge facing east.



Inspection Photos  
Location Name: Renzelman 34-33  
Location ID: 305017



**Photo 3.** Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Renzelman 34-33  
Location ID: 305017



**Photo 4.** Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west.




Inspection Photos  
Location Name: Renzelman 34-33  
Location ID: 305017



**Photo 5.** Well pad reference area.



Inspection Photos  
Location Name: Renzelman 34-33  
Location ID: 305017



**Photo 6.** Overview photo of the access road. Note: portions of access road do not appear properly recontoured/reclaimed.