

Final Reclamation Inspection

September 3rd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 307179

Inspection Document #: 701900652

SESE Section 25 T5N R68W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Laune 44-25
Location ID: 307179




Photo 1. 2021 aerial imagery of the well pad and tank battery.

Inspection Photos
Location Name: Laune 44-25
Location ID: 307179



Photo 2. Overview photo of the well pad and reference area taken from the southern edge facing north using a drone. Note: well pad appears consistent with adjacent crop reference area.

Inspection Photos
Location Name: Laune 44-25
Location ID: 307179




Photo 3. Overview photo of the tank battery taken from directly above the disturbance using a drone. Note: tank battery appears stunted; see elevation model in photo 4.




Photo 4. Plant elevation model of the tank battery. Tank battery shows stunted crop growth and does not appear consistent with adjacent crop reference area.