

Final Reclamation Inspection

September 5th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323356

Inspection Document #: 701900656

SENE Section 23 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Susan 1-23
Location ID: 323356




Photo 1. 2021 aerial imagery of the well pad and tank battery.

Inspection Photos
Location Name: Susan 1-23
Location ID: 323356



Photo 2. Overview photo of the well pad. Note: site was in a no fly zone so photo was taken from the top of a vehicle. No obvious evidence of crop stunting or oil/gas operations.

Inspection Photos
Location Name: Susan 1-23
Location ID: 323356



Photo 3. Overview photo of the tank battery taken at ground level from the eastern edge facing west. Note: tank battery remains with gravel and old culverts/storage.